



See the latest construction progress on [webcam 1](#) and [webcam 2](#).

## Upcoming and ongoing activity: How you may be affected

Area	Impact	Timing
Main Construction Site Internal (STKB)	Furniture installation majority complete Mechanical commissioning has commenced	February
Mary Glowrey Building (MGB) services upgrade	MGB services upgrade works completed, with plastering and painting to be completed. Further detail of disruption to be advised through the university works notifications.	February
MGB Interconnections	Doors between the STKB and MGB and the surrounding walls are being painted and doors commissioned.	February
MGB Façade	Painting completed to Napier, Little Victoria & Young Streets Victoria Parade frontage scaffold erected to complete render and painting.	February
MGB Access	MGB original North entry has re-opened. Signage spans from Victoria Parade and internal MGB advising staff and students of the revised access routes.	February
Main Construction Site external (STKB)	Final concrete pour of pathways upcoming..	February
External perimeter of MGB & STKB	Footpath and street repair works have begun and includes paving, asphalt, kerb and channels.	February
Main Construction Site	Pedestrians should be aware of increased construction vehicle movement. Please expect changes to traffic and pedestrian routes with the assistance of traffic controllers and follow signs and directions.	Ongoing

### The latest in pictures



View from Victoria Pde



Furniture installation in office levels



Reopened MGB North Entry



Tea room on office levels



Please observe direction and safety signs and follow the instructions of Watpac traffic controllers.

If you wish to provide feedback, contact the team at [ACUfeedback@watpac.com.au](mailto:ACUfeedback@watpac.com.au)